

INVITATION TO BID

Project Description: Rau Construction Company is accepting bids for the renovation of the **Historic Federal Reserve** located at 925 Grand, Kansas City Missouri 64106. This will be renovated into a 284room Embassy Suites Hotel. This work also includes the Parking Garage repairs and upgrades to the parking garage located at 10th and McGee. All bids need to be broken out into two separate numbers for tracking, the Hotel building, and the parking garage.

This work includes: Demolition, Saw cutting & coring, Abatement, Site utilities, landscaping, Asphalt Paving, Streetscape, Parking deck repairs and patching, parking and drive lane striping, Concrete, Structural Steel, Masonry, Historic Masonry restoration, Tuckpointing, Caulking, Waterproofing, Roofing, Sheetmetal, interior glass and glazing, Doors / Frames & hardware, specialty doors, Millwork, Flooring, Tile, Painting, Wallcoverings, Framing, Drywall, Ceilings, Insulation, specialties, signage, bathroom accessories, Mechanical, Plumbing, Fire Protection, Electrical, voice / data, low voltage

BID INFORMATION				
Project Name:	Federal Reserve			
Project Address:	925 Gran	925 Grand, Kansas City Missouri 64106		
Bids Due no later than:	Date:	October 14 th , 2020	Time:	4:00pm
Email all bids to:	patti@rauconstruction.com, Jason@Rauconstruction.com, gmeyer@rauconstruction.com			
Fax all bids to:	(913) 642-6031			

Rau Construction Project Contacts: Main point of contact will be Jason Meyer

Jason Meyer	Phone: 913-642-6000 Email:	jason@rauconstruction.com
Gus Meyer	Phone: 913-642-6000 Email:	gmeyer@rauconstruction.com

PLANS			
Electronic Download	We will send you a link to download plans electronically.		
Plan CD	Available for you to pick-up at Rau's office. Please call front desk to reserve a copy		
Hard Set	Available to view at Rau's office		

Instructions to Bidders:

- 1. Submitting Bids All Bids must be FAXED to Rau Construction Co at (913)-642-6031 OR EMAILED to patti@rauconstruction.com, Jason@rauconstruction.com
- 2. MBE/WBE. There will be MBE/WBE goals on this project.
- 3. This project is NOT a tax-exempt project.
- 4. Walkthrough: Wednesday, September 30, 2020 at 10:00 am and Thursday, October 1, 2020 at 2:00 pm and Tuesday, October 6[,] 202 at 10:00 am and Thursday, October 8, 2020 at 9:00 am ***** Due to Covid-19 we will not be having open site visits. Please contact Jason Meyer or Patti with Rau Construction to sign up for one or more of the site visits 913-642-6000
- 5. Questions should be addressed to Jason Meyer at Rau Construction. 913-642-6000.



General Notes:

Rau Construction Company reserves the right to waive minor deficiencies in any bid proposal. Rau Construction Company reserves the right to reject any and all bids. Rau Construction is an Equal Opportunity Employer and encourages the same guidelines from all sub-contractor / suppliers.

Please indicate whether or not you will be bidding this project by replying to this email or calling Patti Dailey or Jason Meyer at (913) 642-6000.

Federal Reserve Bid Documents

Please make sure you have copies of, or have access to all the bid documents:

- Plans: Reserve Bid Set
- Document: Reserve Bid Set Specifications
- Document: Matchline Outline Specification * this document has all the finishes in it
- Plans: Reserve Exterior Restoration
- Document: Reserve Exterior Restoration Specifications
- Plans: Reserve Parking Garage



October 7, 2020

The Grand Reserve Addendum for Bidding #1

 The interior buildout and finishes for the building tower will be bid in 2 phases. The current bid phase, Phase 1 is to include the buildout and finishes for the Hotel Units from floors 5 thru 19. There is work drawn in Phase 1 plans on other floors. This work on other floors is provided for Permitting of the project which is currently underway.

In addition to the Phase 1 plans, bidders should consult the specifications as well as the Matchline Finish Selections document for finish selections and directions.

Phase 1 Bids for interior trades should be limited to construction and finishes on the hotel room floors, floor 5 thru 19.

Additional information for MEP Trades. Note that Alternate Bids in each of these areas will be for future budgeting purposes. Base bids are for work on Floors 5 thru 19 and will be used to evaluate bidders for Phase #1.

- a) Plumbing
 - i) Base Bid
 - (1) Provide all new vertical risers as shown for water, waste and vent, roof drains from 5 thru 19. Continuations of these risers will be in Phase 2
 - (2) Provide all plumbing as shown for floors 5 thru 19
 - ii) Plumbing Alternate #1
 - (1) Provide plumbing as shown on balance of Phase 1 drawings on the Basement thru 4th Floors and 20th thru Roof.
- b) HVAC
 - i) Base Bid
 - (1) Provide all HVAC shown on the Phase 1 plans for floors 5 thru 19.
 - (2) Hydronic piping on floors 5 thru 19 starts from existing risers. Assume vertical CW and HW risers are existing and in usable condition.
 - ii) HVAC Alternate #1
 - (1) Provide HVAC as shown on the balance of the Phase 1 drawings on the Basement thru 4th Floors and 20th Floor.
 - (2) Assume vertical CW and HW hydronic mains in Main Building are existing and in usable condition. All other hydronic piping shown including horizontal mains to be new.
 - (3) Provide pricing for new major equipment as drawn and scheduled on the Basement thru 4th Floors and 20th Floor thru Roof

October 7, 2020 The Grand Reserve Addendum for Bidding #1 Page 2

- c) Fire Sprinklers
 - i) Base Bid Provide fire sprinkler pricing for fire sprinklers on floors 5 thru 19 including vertical mains on those floors.
 - ii) Fire Sprinkler Alternate #1 Provide fire sprinkler pricing for base systems and fire sprinklers for areas shown to be included in Phase 1 on the Basement thru 4th Floors and 20th Floor thru Roof
- d) Electrical
 - i) Base Bid
 - Reuse the Buss Duct in the Northeast corner of the tower to feed the North portion of Floors 5 thru 19 as shown. Provide feeds from DPT3B on the Tower Third Floor B to floor 5 thru 19 as shown including gear DPT3B. Feed to gear DPT3B to be in Phase 2
 - (2) Provide all Electrical as shown for floors 5 thru 19
 - ii) Electrical Alternate #1
 - (1) Provide Electrical as shown on balance of Phase 1 drawings on the Basement thru 4th Floors and 20th thru Roof.
 - (2) All work not shown on the Basement thru 4th Floors and 20th thru Roof including Data, Voice, MATC, Security, etc will be in Phase 2
 - (3) Provide 400 KW diesel generator on Third Floor roof.
 - iii) Electrical Alternate #2
 - (1) Provide allowance to feed MEP equipment as shown but not detailed to date.
- 2) Guest Rooms Questions
 - a) Do tubs get curved shower rods and showers get glass shower doors? Answer: Tubs get shower rods and Showers (ADA units) get shower doors.
 - b) Provide listing and specifications for Toilet Accessories. Answer:
 - i) Robe Hook to be Wingit Innovations (517-225-5225) model WMEGDRH Modern Elegance Grand Double Robe Hook, Polishes Stainless Steel. 2 per Guestroom Bath
 - ii) Towel Bar to be Delta Faucet (972-881-8757) model 77618 Stryke Towel Bar, 18" Towel Bar, Chrome. 1 per Guest Bath
 - iii) Decorative Tower Bar to be Wingit Innovations (517-225-5225) model WGB5XE Modern Elegance 24" OAL, Polished Stainless Steel. 1 per Guestroom Bath
 - iv) Toilet Paper Holder to be Delta Faucet (972-881-8757) model #77655 Stryke Tissue Holder, Chrome. 1 per Guest Bath
 - v) Soap Dish @ Tub/Shower to be Wingit Innovations (517-225-5225) model WCB2 Master Basket Corner, 8", Polished Stainless Steel. 1 per Guest Bath.
 - c) How tall are the corner guards? Answer: Full height

October 7, 2020 The Grand Reserve Addendum for Bidding #1 Page 3

- d) Per Section 08 14 16 Flush Wood Doors Summary 1.2 says doors are Factory Finished. Section 2.7 implies the doors are primed for Opaque Finish (in the field). Are interior wooden doors, barn doors and wooden frames other than room entry doors to be factory finished? Answer: Flush wood doors including interior wood doors, barn doors and associated wood frames to be factory primed and field painted
- e) Is there any waterproofing/ Crack Isolation required at bath/entry floors under the tile? If so, what is the product? Answer: Yes. Specifications will be provided but probably not until after the bid date. Products to comply with ANSI A118.10 and installation to ANSI A108.17.
- f) Is there waterproofing required at shower walls? Answer: Yes. Specifications will be provided but probably not until after the bid date. Products to comply with ANSI A118.17 and installation to ANSI A108.13.
- g) Is the grout for the tile standard Portland cement grout? Any specialty grouts? Answer: There are no specialty grouts in Phase 1. Grout in Phase 1 will be standard grout in one of manufacturers standard colors.
- h) Is it OK to provide sealant at all tile vertical inside corners in lieu of grout? Answer: Grout corners.
- i) Should TR03 tile termination be used at the shower outside corners? Answer: Correct, outside corner (edge) only
- j) Does TR04 sit on top of the TB01 base? Answer: TR04 does sit on top of base and acts as a vertical transition of tub/shower wall tile and wallcovering.
- 3) Parking Garage
 - a) Structural repairs should be bid as a "design/build" package including engineer fees to design, monitor and support repairs per General Note #20 on the Construction Documents – Garage Maintenance plans dated May 3, 2019
 - b) Refer to the Garage Repair Plans dated January 25, 2019 numbered S401-G thru S408-G for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.

October 7, 2020 The Grand Reserve Addendum for Bidding #1 Page 4


- c) Bids should include Items listed Garage Key Repair Notes Items 1 thru 6 as noted on the January 25, 2019 plans. Quantities listed in Estimated Quantities in the bid matrix attached should be included in your bid. If you propose alternative quantities, please describe rationale for proposed alternative quantities. In addition to these items, Other Repairs as noted below should include repairs to curbs, wall cracks on level L & M, and other repairs that should be described in your bid.
- d) Plans on Garage Level sheets have a 1/A2.11 callout typically around grid G-9. What is this? Answer: Please disregard this callout.
- e) Overhead Doors GL100A and GL100B have note 21 which calls out to remove doors. Door schedule has these doors as Remain and Repair. Should these doors be removed? Answer: Price to remain and repair.
- f) Key Note #15 calls to evaluate handrails and amend to meet code. If this is a repair package, does code require these changes? Answer: Since this is a repair package, these should not be required to be brought up to code. Please provide an alternate to replace the center handrail/guardrail system with a system that meets code.
- g) Key Note #19 calls to remove and replace powered wayfinding signage. Any more information on this. Answer: Provide lighted system similar to existing. Price as an alternate.
- 4) Bid Date and Time
 - a) The bid date shall be extended to Friday, October 16, 2020. Bid time shall remain at 4:00 pm.

Attachments Parking Garage Repair Plans dated January 25, 2019 Parking Garage Repair Bid Form


The Grand Reserve Parking Garage Structural Repairs Bid Form

Plan Key


Repair		Estimated		Bid	Unit Price Used	
Items	Description	Quantities	Units	Amount	For Bid Adjustm	ents
	Mobilization/demobilization	1	lsum	\$	N/A	
1	Surface Slab Spall	10,700	sf	\$	\$	/sf
2	Overhead Slab Spall	1,000	sf	\$	\$	/sf
3	Overhead Beam Spall	400	sf	\$	\$	/sf
4	Slab Full Depth/Deep Repair	350	sf	\$	\$	/sf
5	Expansion Joint Remove/Replace	68	lf	\$	\$	/sf
6	Traffic Coating (in 1, 4, 5 above)	11,186	sf	\$	\$	/sf
	Other Repairs	1	lsum	\$	N/A	
	Engineering	1	lsum	\$	N/A	
	Total Base Bid			\$		
Alt #1a	Remove/Replace balance of Traffic					
	Coating (not in 1, 4 & 5 above) on					
	Decks K & L		sf	\$	\$	/sf
Alt #1b	Remove/Replace balance of Traffic					
	Coatings (not in 1, 4 & 5 above) on					
	Decks A thru K		sf	\$	\$	/sf
Alt #2	Remove/Replace balance of expansion					
	Joint along D line (not in 5 above)		lf	\$	\$	/lf



I.



I.



<u>NORTH</u>



1

GARAGE REPAIR KEY NOTES

SEE TYPICAL PATCH BOUNDARY, REBAR UNDERCUTTING AND PATCH DETAILS 1/S407-G, 2/S407-G, 3/S407-G

REPAIR (1) <u>SURFACE SLAB SPALL</u> - 1/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 1/S408-G.

REMOVE THE EXISTING TRAFFIC COATING OVER THE SPALLED AREA. REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED. **REPAIR** (2) <u>OVERHEAD SLAB SPALL</u> - 2/S408-G

EXAMINE THE UNDERSIDE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 2/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (3) <u>OVERHEAD BEAM SPALL</u> - 3/S408-G

EXAMINE THE UNDERSIDE OF THE BEAM WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF BEAM SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 3/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S

INSTRUCTIONS. AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (4) <u>SLAB FULL DEPTH REPAIR</u> - 4/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF FULL DEPTH SLAB HOLES.

REMOVE WATER, DEBRIS AND SPALLED OR DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. FILL THE FORM VOID WITH STYROFOAM TO CONTAIN THE PATCH MATERIAL AND FORM THE UNDERSIDE OF THE PATCH. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER THE REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

REPAIR (5) <u>EXPANSION JOINT REMOVAL AND REPLACEMENT</u> SEE ALTERNATE #2 - EXCEPT RAMPS BETWEEN LEVELS 'M' AND 'L'

REMOVE DAMAGED THE VERTICAL AND HORIZONTAL JOINT MATERIAL AND THOROUGHLY CLEAN THE JOINTS ACCORDING TO THE JOINT MATERIAL MANUFACTURER'S WRITTEN INSTRUCTIONS. ENSURE THAT THE CONCRETE ON EITHER SIDE AND AROUND THE JOINT IS SOUND, STABLE AND IN A CONDITION TO RECEIVE THE NEW JOINT MATERIAL. PLACE THE NEW JOINT MATERIAL ACCORDING TO THE JOINT MANUFACTURER'S WRITTEN INSTRUCTIONS, INCLUDING CLEANING, PRIMING, INSTALLATION AND CURING

REPAIR (6) <u>NEW TRAFFIC COATING</u>

CLEAN THE DESIGNATED AREA OF EXISTING TRAFFIC COATING DOWN TO A STABLE CLEAN CONCRETE SURFACE. MAKE SLAB REPAIRS ACCORDING TO THE REPAIR KEY NOTES AS INDICATED ON THE DRAWINGS. APPLY PRIMER TO THE EXPOSED CONCRETE ACCORDING TO THE MANUFACTURER'S WRITTEN INSTRUCTIONS. APPLY THE LAYERS OF TRAFFIC COATING ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS AND THE SPECIFICATIONS. OVERLAP THE NEW COATING ONTO THE EXISTING COATING MIN OF 12" AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

GARAGE REPAIR GENERAL NOTES

- 1. THE GARAGE LAYOUT SHOWN ON THE REPAIR PLANS WAS TAKEN FROM EXISTING DRAWINGS AND MAY NOT ACCURATELY REFLECT AS-BUILT CONDITIONS. REPORT SIGNIFICANT VARIATIONS BETWEEN THE PLANS AND FIELD CONDITIONS TO THE ARCHITECT/ENGINEER. 2. CONTRACTOR TO EXAMINE THE ENTIRE GARAGE PRIOR TO MAKING REPAIRS AND BECOME
- FAMILIAR WITH EXISTING CONDITIONS. CONTRACTOR TO REPORT TO THE ARCHITECT/ENGINEER IF CONDITIONS ARE FOUND THAT MAY PREVENT THE WORK FROM BEING PERFORMED ACCORDING TO THE DRAWINGS AND SPECIFICATIONS. 3. CONTRACTOR TO COORDINATE THE WORK WITH THE PARKING GARAGE OWNER/OPERATOR
- REGARDING CLOSURE OF AREAS OF THE GARAGE AS REQUIRED TO MAKE THE REPAIRS. WORK SHALL BE PERFORMED ONLY AT NIGHT DURING OFF HOURS IF DESIGNATED BY THE OWNER/OPERATOR.
- 4. THE GENERAL FLOOR DECK FRAMING OF THIS PARKING GARAGE CONSISTS OF CAST-IN-PLACE, POST-TENSIONED SLABS AND BEAMS. THE SLABS ARE APPROXIMATELY 25" DEEP WITH FORM VOIDS THAT CREATE 6" WIDE CONCRETE JOISTS AT APPROXIMATELY 25" TO 26" ON CENTER. THESE JOISTS ARE REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. THE BEAMS ARE ALSO REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. UNDER NO CIRCUMSTANCES ARE THE P/T STRANDS TO BE DISTURBED, CUT, NICKED OR DAMAGED. IF DAMAGE TO P/T STRANDS IS DISCOVERED DURING THE COURSE OF THE PROJECT, STOP WORK IN THE AREA OF THE DAMAGED
- STRANDS AND REPORT TO THE ARCHITECT/ENGINEER IMMEDIATELY. 5. CONTRACTOR SHALL PROVIDE SHORING, DESIGNED BY A SHORING CONTRACTOR, FOR BEAM SPALL REPAIRS. SHORING SHALL EXTEND DOWN NO LESS THAN THREE LEVELS BELOW THE LEVEL OF THE BEAM UNDER REPAIR. 6. REFER TO THE WRITTEN SPECIFICATIONS AND MANUFACTURER'S WRITTEN INSTRUCTIONS FOR
- APPLICATION OF EACH REPAIR MATERIAL. A TECHNICAL REPRESENTATIVE FROM EACH OF THE REPAIR MATERIAL MANUFACTURER'S SHALL VISIT THE SITE AND PROVIDE SITE SPECIFIC INSTRUCTIONS. OBSERVE THE AMBIENT TEMPERATURE LIMITATIONS FOR APPLICATION OF EACH MATERIAL 7. PROTECT THE GARAGE AND GARAGE CONTENTS THROUGHOUT THE COURSE OF THE WORK. DO
- NOT DAMAGE VEHICLES DURING THE COURSE OF THE WORK. SUCH DAMAGE SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR. 8. FIELD LOCATE MECHANICAL EQUIPMENT, AIR INTAKE LOUVERS, EXHAUST LOUVERS OR OTHER HVAC EQUIPMENT THAT MAY BE DAMAGED BY DUST AND DEBRIS AND PROVIDE ADEQUATE FILTERS
- AND PROTECTION. DO NOT ALLOW DUST AND DEBRIS TO ENTER OCCUPIED SPACE IN THE BUILDINGS UNDER AND/OR ATTACHED TO THIS PARKING GARAGE. CONTAIN DUST AND DEBRIS FROM ESCAPING THE GARAGE AND INTO ADJACENT BUILDINGS OR THE PUBLIC ACCESS AROUND THE BUILDING. 9. THIS PARKING GARAGE IS SITUATED OVER BASEMENT LEVELS THAT ARE BELOW GRADE. PROTECT
- THESE BASEMENT LEVELS FROM DAMAGE AS A RESULT OF THE REPAIR WORK. CONTRACTOR SHALL BECOME FAMILIAR WITH THE BASEMENT LEVELS AND TAKE PRECAUTIONS AS NEEDED TO PROTECT THE SAME. 10. DO NOT USE EXCESSIVE WATER TO CLEAN, BLAST OR PRESSURE WASH THE GARAGE FLOORS
- THAT MAY LEAK INTO THE BASEMENTS BELOW. ENSURE THAT THE FLOOR DRAINS ARE CLEAN AND IN GOOD WORKING ORDER TO ENSURE THAT WATER, IF NEEDED, IS PROPERLY MANAGED. 11. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER FLOOR MARKINGS AS REQUIRED WHERE EXISTING MARKINGS ARE REMOVED OR DISTURBED BY THE SLAB REPAIR AND REPLACEMENT COATING WORK. OWNER/OPERATOR TO PROVIDE MARKINGS AS REQUIRED FOR OPERATION OF THE GARAGE.

ALTERNATES

ALTERNATE #1 - 100% REMOVAL AND REPLACEMENT OF THE TRAFFIC COATING

REMOVE AND REPLACE 100% OF THE EXISTING TRAFFIC COATING USING A METHOD APPROPRIATE TO THE EXISTING CONCRETE CONDITIONS AND WHICH WILL RESULT IN A SURFACE THAT IS ACCEPTABLE FOR APPLICATION OF A NEW TRAFFIC COATING AS DIRECTED BY THE COATING MANUFACTURER. MAKE STRUCTURAL REPAIRS TO THE CONCRETE SLAB AS INDICATED ON THE DRAWINGS AND

ACCORDING TO THE REPAIR KEY NOTES BEFORE PREPARATION AND APPLICATION OF THE NEW TRAFFIC COATING. AFTER REPAIR AND PREPARATION AND CURING OF THE CONCRETE SURFACES, APPLY A NEW TRAFFIC

COATING OVER 100% OF THE EXPOSED CONCRETE SLAB SURFACE AND 100% OF THE CURBS AND WALKWAYS. APPLY TO THE HORIZONTAL AND VERTICAL SURFACES OF THE CURBS AND WALKWAYS. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER MARKINGS AFTER THE NEW TRAFFIC COATING IS APPLIED AND COMPLETELY CURED.

ALTERNATE #2 - 100% REMOVAL AND REPLACEMENT OF THE RAMP EXPANSION JOINTS SEE KEY NOTE 5. REMOVE AND REPLACE 100% OF THE EXISTING RAMP HORIZONTAL AND VERTICAL EXPANSION JOINTS AT ALL LEVELS. **NOTE:** REPLACEMENT OF EXPANSION JOINTS AT THE SKYWARD RAMPS BETWEEN LEVELS 'M' AND 'L' ARE TO BE CONSIDERED IN THE BASE BID.

BROWNING DAY MULLINS DIERDORF LEADERSHIP + DESIGN®

Browning Day Mullins Dierdorf Architects Architecture Landscape Architecture Planning Interior Design

626 North Illinois Street Indianapolis, Indiana 46204 Phone: (317) 635-5030 Website: www.bdmd.com

Delta Quad Holdings, LLC

Rau Construction Co. Construction Manager 9101 West 110th Street, Suite 150

Overland Park, Kansas 66210 Phone: (913) 642-6000 Website: www.website.com

Lawson Elser, Inc. Structural Engineer

650 East Carmel Drive, Suite 150 Carmel, Indiana 46032 Phone: (317) 574-5409 Website: www.lawsonelser.com

Hoss & Brown Engineers, Inc. MEP Engineer

11205 West 79th Street, Suite 102 Lenexa, Kansas 66214 Phone: (913) 362-9090 Website: www.h-be.com

SK Design Group, Inc. Civil Engineer 4600 College Boulevard, Suite 100

Overland Park, KS 66211 Phone: (913) 451-1818 Website: www.skdesigngroup.com

Matchline Design Group, LLC Interior Design 10300 North Central Expressway, Suite 335 Dallas, TX 75231


Phone: (972) 707-0568 Website: www.matchlinedesign.com


Garage Repair Plans dated January 25, 2019 are for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.

> CERTIFICATION GARAGE MAINTENANCE PACKAGE

The Grand Reserve









GARAGE REPAIR KEY NOTES

SEE TYPICAL PATCH BOUNDARY, REBAR UNDERCUTTING AND PATCH DETAILS 1/S407-G, 2/S407-G, 3/S407-G

REPAIR (1) <u>SURFACE SLAB SPALL</u> - 1/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 1/S408-G.

REMOVE THE EXISTING TRAFFIC COATING OVER THE SPALLED AREA. REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE, BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF, DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED. **REPAIR** (2) <u>OVERHEAD SLAB SPALL</u> - 2/S408-G

EXAMINE THE UNDERSIDE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 2/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (3) OVERHEAD BEAM SPALL - 3/S408-G

EXAMINE THE UNDERSIDE OF THE BEAM WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF BEAM SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 3/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (4) <u>SLAB FULL DEPTH REPAIR</u> - 4/S408-G EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF FULL DEPTH SLAB HOLES.

REMOVE WATER, DEBRIS AND SPALLED OR DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. FILL THE FORM VOID WITH STYROFOAM TO CONTAIN THE PATCH MATERIAL AND FORM THE UNDERSIDE OF THE PATCH. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER THE REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

REPAIR (5) <u>EXPANSION JOINT REMOVAL AND REPLACEMENT</u> SEE ALTERNATE #2 - EXCEPT RAMPS BETWEEN LEVELS 'M' AND 'L'

REMOVE DAMAGED THE VERTICAL AND HORIZONTAL JOINT MATERIAL AND THOROUGHLY CLEAN THE JOINTS ACCORDING TO THE JOINT MATERIAL MANUFACTURER'S WRITTEN INSTRUCTIONS. ENSURE THAT THE CONCRETE ON EITHER SIDE AND AROUND THE JOINT IS SOUND, STABLE AND IN A CONDITION TO RECEIVE THE NEW JOINT MATERIAL. PLACE THE NEW JOINT MATERIAL ACCORDING TO THE JOINT MANUFACTURER'S WRITTEN INSTRUCTIONS, INCLUDING CLEANING, PRIMING, INSTALLATION AND CURING.

REPAIR 6 <u>NEW TRAFFIC COATING</u>

<u>NORTH</u>

CLEAN THE DESIGNATED AREA OF EXISTING TRAFFIC COATING DOWN TO A STABLE CLEAN CONCRETE SURFACE. MAKE SLAB REPAIRS ACCORDING TO THE REPAIR KEY NOTES AS INDICATED ON THE DRAWINGS. APPLY PRIMER TO THE EXPOSED CONCRETE ACCORDING TO THE MANUFACTURER'S WRITTEN INSTRUCTIONS. APPLY THE LAYERS OF TRAFFIC COATING ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS AND THE SPECIFICATIONS. OVERLAP THE NEW COATING ONTO THE EXISTING COATING MIN OF 12" AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

GARAGE REPAIR GENERAL NOTES

- 1. THE GARAGE LAYOUT SHOWN ON THE REPAIR PLANS WAS TAKEN FROM EXISTING DRAWINGS AND MAY NOT ACCURATELY REFLECT AS-BUILT CONDITIONS. REPORT SIGNIFICANT VARIATIONS BETWEEN THE PLANS AND FIELD CONDITIONS TO THE ARCHITECT/ENGINEER. 2. CONTRACTOR TO EXAMINE THE ENTIRE GARAGE PRIOR TO MAKING REPAIRS AND BECOME
- FAMILIAR WITH EXISTING CONDITIONS. CONTRACTOR TO REPORT TO THE ARCHITECT/ENGINEER IF CONDITIONS ARE FOUND THAT MAY PREVENT THE WORK FROM BEING PERFORMED ACCORDING TO THE DRAWINGS AND SPECIFICATIONS. 3. CONTRACTOR TO COORDINATE THE WORK WITH THE PARKING GARAGE OWNER/OPERATOR
- REGARDING CLOSURE OF AREAS OF THE GARAGE AS REQUIRED TO MAKE THE REPAIRS. WORK SHALL BE PERFORMED ONLY AT NIGHT DURING OFF HOURS IF DESIGNATED BY THE OWNER/OPERATOR.
- 4. THE GENERAL FLOOR DECK FRAMING OF THIS PARKING GARAGE CONSISTS OF CAST-IN-PLACE, POST-TENSIONED SLABS AND BEAMS. THE SLABS ARE APPROXIMATELY 25" DEEP WITH FORM VOIDS THAT CREATE 6" WIDE CONCRETE JOISTS AT APPROXIMATELY 25" TO 26" ON CENTER. THESE JOISTS ARE REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. THE BEAMS ARE ALSO REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. UNDER NO CIRCUMSTANCES ARE THE P/T STRANDS TO BE DISTURBED, CUT, NICKED OR DAMAGED. IF DAMAGE TO P/T STRANDS IS DISCOVERED DURING THE COURSE OF THE PROJECT, STOP WORK IN THE AREA OF THE DAMAGED STRANDS AND REPORT TO THE ARCHITECT/ENGINEER IMMEDIATELY.
- 5. CONTRACTOR SHALL PROVIDE SHORING, DESIGNED BY A SHORING CONTRACTOR, FOR BEAM SPALL REPAIRS. SHORING SHALL EXTEND DOWN NO LESS THAN THREE LEVELS BELOW THE LEVEL OF THE BEAM UNDER REPAIR. 6. REFER TO THE WRITTEN SPECIFICATIONS AND MANUFACTURER'S WRITTEN INSTRUCTIONS FOR
- APPLICATION OF EACH REPAIR MATERIAL. A TECHNICAL REPRESENTATIVE FROM EACH OF THE REPAIR MATERIAL MANUFACTURER'S SHALL VISIT THE SITE AND PROVIDE SITE SPECIFIC INSTRUCTIONS. OBSERVE THE AMBIENT TEMPERATURE LIMITATIONS FOR APPLICATION OF EACH MATERIAL. 7. PROTECT THE GARAGE AND GARAGE CONTENTS THROUGHOUT THE COURSE OF THE WORK. DO
- NOT DAMAGE VEHICLES DURING THE COURSE OF THE WORK. SUCH DAMAGE SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR. 8. FIELD LOCATE MECHANICAL EQUIPMENT, AIR INTAKE LOUVERS, EXHAUST LOUVERS OR OTHER HVAC EQUIPMENT THAT MAY BE DAMAGED BY DUST AND DEBRIS AND PROVIDE ADEQUATE FILTERS AND PROTECTION. DO NOT ALLOW DUST AND DEBRIS TO ENTER OCCUPIED SPACE IN THE
- BUILDINGS UNDER AND/OR ATTACHED TO THIS PARKING GARAGE. CONTAIN DUST AND DEBRIS FROM ESCAPING THE GARAGE AND INTO ADJACENT BUILDINGS OR THE PUBLIC ACCESS AROUND THE BUILDING. 9. THIS PARKING GARAGE IS SITUATED OVER BASEMENT LEVELS THAT ARE BELOW GRADE. PROTECT
- THESE BASEMENT LEVELS FROM DAMAGE AS A RESULT OF THE REPAIR WORK. CONTRACTOR SHALL BECOME FAMILIAR WITH THE BASEMENT LEVELS AND TAKE PRECAUTIONS AS NEEDED TO PROTECT THE SAME. 10. DO NOT USE EXCESSIVE WATER TO CLEAN, BLAST OR PRESSURE WASH THE GARAGE FLOORS
- THAT MAY LEAK INTO THE BASEMENTS BELOW. ENSURE THAT THE FLOOR DRAINS ARE CLEAN AND IN GOOD WORKING ORDER TO ENSURE THAT WATER, IF NEEDED, IS PROPERLY MANAGED. 11. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER FLOOR MARKINGS AS REQUIRED WHERE EXISTING MARKINGS ARE REMOVED OR DISTURBED BY THE SLAB REPAIR AND REPLACEMENT COATING WORK. OWNER/OPERATOR TO PROVIDE MARKINGS AS

ALTERNATES

TRAFFIC COATING.

REQUIRED FOR OPERATION OF THE GARAGE.

ALTERNATE #1 - 100% REMOVAL AND REPLACEMENT OF THE TRAFFIC COATING

REMOVE AND REPLACE 100% OF THE EXISTING TRAFFIC COATING USING A METHOD APPROPRIATE TO THE EXISTING CONCRETE CONDITIONS AND WHICH WILL RESULT IN A SURFACE THAT IS ACCEPTABLE FOR APPLICATION OF A NEW TRAFFIC COATING AS DIRECTED BY THE COATING MANUFACTURER. MAKE STRUCTURAL REPAIRS TO THE CONCRETE SLAB AS INDICATED ON THE DRAWINGS AND ACCORDING TO THE REPAIR KEY NOTES BEFORE PREPARATION AND APPLICATION OF THE NEW

AFTER REPAIR AND PREPARATION AND CURING OF THE CONCRETE SURFACES, APPLY A NEW TRAFFIC COATING OVER 100% OF THE EXPOSED CONCRETE SLAB SURFACE AND 100% OF THE CURBS AND WALKWAYS. APPLY TO THE HORIZONTAL AND VERTICAL SURFACES OF THE CURBS AND WALKWAYS. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER MARKINGS AFTER THE NEW TRAFFIC COATING IS APPLIED AND COMPLETELY CURED.

ALTERNATE #2 - 100% REMOVAL AND REPLACEMENT OF THE RAMP EXPANSION JOINTS SEE KEY NOTE 5. REMOVE AND REPLACE 100% OF THE EXISTING RAMP HORIZONTAL AND VERTICAL EXPANSION JOINTS AT ALL LEVELS. NOTE: REPLACEMENT OF EXPANSION JOINTS AT THE SKYWARD RAMPS BETWEEN LEVELS 'M' AND 'L' ARE TO BE CONSIDERED IN THE BASE BID.

BROWNING DAY MULLINS DIERDORF LEADERSHIP + DESIGN®

Browning Day Mullins Dierdorf Architects Architecture Landscape Architecture Planning Interior Design

626 North Illinois Street Indianapolis, Indiana 46204 Phone: (317) 635-5030 Website: www.bdmd.com

Delta Quad Holdings, LLC Owne

Rau Construction Co. Construction Manager 9101 West 110th Street, Suite 150

Overland Park, Kansas 66210 Phone: (913) 642-6000 Website: www.website.com

Lawson Elser, Inc. Structural Engineer 650 East Carmel Drive, Suite 150

Carmel, Indiana 46032 Phone: (317) 574-5409 Website: www.lawsonelser.com

Hoss & Brown Engineers, Inc. MEP Engineer

11205 West 79th Street, Suite 102 Lenexa, Kansas 66214 Phone: (913) 362-9090 Website: www.h-be.com

SK Design Group, Inc. Civil Engineer 4600 College Boulevard, Suite 100

Overland Park, KS 66211 Phone: (913) 451-1818 Website: www.skdesigngroup.com

Matchline Design Group, LLC Interior Design 10300 North Central Expressway, Suite 335 Dallas, TX 75231

Phone: (972) 707-0568 Website: www.matchlinedesign.com


Garage Repair Plans dated January 25, 2019 are for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.


> CERTIFICATION GARAGE MAINTENANCE PACKAGE

The Grand Reserve

925 Grand Boulevard Kansas City, MO 64198				
Project No.: LEI #1851 Drawn By: Checked By: MjL Scale: See Drawing Issue Date: January 25, 2019				
REVISION SCHEDULE				
Rev. #	Rev. # Revision Description Issue Date			







_

<u>NORTH</u>



GARAGE REPAIR KEY NOTES

SEE TYPICAL PATCH BOUNDARY, REBAR UNDERCUTTING AND PATCH DETAILS 1/S407-G, 2/S407-G, 3/S407-G

REPAIR (1) <u>SURFACE SLAB SPALL</u> - 1/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 1/S408-G.

REMOVE THE EXISTING TRAFFIC COATING OVER THE SPALLED AREA. REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED. **REPAIR** (2) <u>OVERHEAD SLAB SPALL</u> - 2/S408-G

EXAMINE THE UNDERSIDE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 2/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (3) OVERHEAD BEAM SPALL - 3/S408-G

EXAMINE THE UNDERSIDE OF THE BEAM WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF BEAM SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 3/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (4) <u>SLAB FULL DEPTH REPAIR -</u> 4/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF FULL DEPTH SLAB HOLES.

REMOVE WATER, DEBRIS AND SPALLED OR DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. FILL THE FORM VOID WITH STYROFOAM TO CONTAIN THE PATCH MATERIAL AND FORM THE UNDERSIDE OF THE PATCH. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER THE REPAIRS ARE COMPLETED AND FULLY CURED. PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

REPAIR (5) <u>EXPANSION JOINT REMOVAL AND REPLACEMENT</u> SEE ALTERNATE #2 - EXCEPT RAMPS BETWEEN LEVELS 'M' AND 'L'

REMOVE DAMAGED THE VERTICAL AND HORIZONTAL JOINT MATERIAL AND THOROUGHLY CLEAN THE JOINTS ACCORDING TO THE JOINT MATERIAL MANUFACTURER'S WRITTEN INSTRUCTIONS. ENSURE THAT THE CONCRETE ON EITHER SIDE AND AROUND THE JOINT IS SOUND, STABLE AND IN A CONDITION TO RECEIVE THE NEW JOINT MATERIAL. PLACE THE NEW JOINT MATERIAL ACCORDING TO THE JOINT MANUFACTURER'S WRITTEN INSTRUCTIONS, INCLUDING CLEANING, PRIMING, INSTALLATION AND CURING.

REPAIR (6) <u>NEW TRAFFIC COATING</u>

CLEAN THE DESIGNATED AREA OF EXISTING TRAFFIC COATING DOWN TO A STABLE CLEAN CONCRETE SURFACE. MAKE SLAB REPAIRS ACCORDING TO THE REPAIR KEY NOTES AS INDICATED ON THE DRAWINGS. APPLY PRIMER TO THE EXPOSED CONCRETE ACCORDING TO THE MANUFACTURER'S WRITTEN INSTRUCTIONS. APPLY THE LAYERS OF TRAFFIC COATING ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS AND THE SPECIFICATIONS. OVERLAP THE NEW COATING ONTO THE EXISTING COATING MIN OF 12" AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

GARAGE REPAIR GENERAL NOTES

- 1. THE GARAGE LAYOUT SHOWN ON THE REPAIR PLANS WAS TAKEN FROM EXISTING DRAWINGS AND MAY NOT ACCURATELY REFLECT AS-BUILT CONDITIONS. REPORT SIGNIFICANT VARIATIONS BETWEEN THE PLANS AND FIELD CONDITIONS TO THE ARCHITECT/ENGINEER. 2. CONTRACTOR TO EXAMINE THE ENTIRE GARAGE PRIOR TO MAKING REPAIRS AND BECOME
- FAMILIAR WITH EXISTING CONDITIONS. CONTRACTOR TO REPORT TO THE ARCHITECT/ENGINEER IF CONDITIONS ARE FOUND THAT MAY PREVENT THE WORK FROM BEING PERFORMED ACCORDING TO THE DRAWINGS AND SPECIFICATIONS. 3. CONTRACTOR TO COORDINATE THE WORK WITH THE PARKING GARAGE OWNER/OPERATOR
- REGARDING CLOSURE OF AREAS OF THE GARAGE AS REQUIRED TO MAKE THE REPAIRS. WORK SHALL BE PERFORMED ONLY AT NIGHT DURING OFF HOURS IF DESIGNATED BY THE OWNER/OPERATOR.
- 4. THE GENERAL FLOOR DECK FRAMING OF THIS PARKING GARAGE CONSISTS OF CAST-IN-PLACE, POST-TENSIONED SLABS AND BEAMS. THE SLABS ARE APPROXIMATELY 25" DEEP WITH FORM VOIDS THAT CREATE 6" WIDE CONCRETE JOISTS AT APPROXIMATELY 25" TO 26" ON CENTER. THESE JOISTS ARE REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. THE BEAMS ARE ALSO REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. UNDER NO CIRCUMSTANCES ARE THE P/T STRANDS TO BE DISTURBED, CUT, NICKED OR DAMAGED. IF DAMAGE TO P/T STRANDS IS DISCOVERED DURING THE COURSE OF THE PROJECT, STOP WORK IN THE AREA OF THE DAMAGED
- STRANDS AND REPORT TO THE ARCHITECT/ENGINEER IMMEDIATELY. 5. CONTRACTOR SHALL PROVIDE SHORING, DESIGNED BY A SHORING CONTRACTOR, FOR BEAM SPALL REPAIRS. SHORING SHALL EXTEND DOWN NO LESS THAN THREE LEVELS BELOW THE LEVEL OF THE BEAM UNDER REPAIR. 6. REFER TO THE WRITTEN SPECIFICATIONS AND MANUFACTURER'S WRITTEN INSTRUCTIONS FOR
- APPLICATION OF EACH REPAIR MATERIAL. A TECHNICAL REPRESENTATIVE FROM EACH OF THE REPAIR MATERIAL MANUFACTURER'S SHALL VISIT THE SITE AND PROVIDE SITE SPECIFIC INSTRUCTIONS. OBSERVE THE AMBIENT TEMPERATURE LIMITATIONS FOR APPLICATION OF EACH MATERIAL.
- 7. PROTECT THE GARAGE AND GARAGE CONTENTS THROUGHOUT THE COURSE OF THE WORK. DO NOT DAMAGE VEHICLES DURING THE COURSE OF THE WORK. SUCH DAMAGE SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR. 8. FIELD LOCATE MECHANICAL EQUIPMENT, AIR INTAKE LOUVERS, EXHAUST LOUVERS OR OTHER
- HVAC EQUIPMENT THAT MAY BE DAMAGED BY DUST AND DEBRIS AND PROVIDE ADEQUATE FILTERS AND PROTECTION. DO NOT ALLOW DUST AND DEBRIS TO ENTER OCCUPIED SPACE IN THE BUILDINGS UNDER AND/OR ATTACHED TO THIS PARKING GARAGE. CONTAIN DUST AND DEBRIS FROM ESCAPING THE GARAGE AND INTO ADJACENT BUILDINGS OR THE PUBLIC ACCESS AROUND THE BUILDING.
- 9. THIS PARKING GARAGE IS SITUATED OVER BASEMENT LEVELS THAT ARE BELOW GRADE. PROTECT THESE BASEMENT LEVELS FROM DAMAGE AS A RESULT OF THE REPAIR WORK. CONTRACTOR SHALL BECOME FAMILIAR WITH THE BASEMENT LEVELS AND TAKE PRECAUTIONS AS NEEDED TO PROTECT THE SAME. 10. DO NOT USE EXCESSIVE WATER TO CLEAN, BLAST OR PRESSURE WASH THE GARAGE FLOORS
- THAT MAY LEAK INTO THE BASEMENTS BELOW. ENSURE THAT THE FLOOR DRAINS ARE CLEAN AND IN GOOD WORKING ORDER TO ENSURE THAT WATER, IF NEEDED, IS PROPERLY MANAGED. 11. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER FLOOR MARKINGS AS REQUIRED WHERE EXISTING MARKINGS ARE REMOVED OR DISTURBED BY THE SLAB REPAIR AND REPLACEMENT COATING WORK. OWNER/OPERATOR TO PROVIDE MARKINGS AS REQUIRED FOR OPERATION OF THE GARAGE.

<u>ALTERNATES</u>

ALTERNATE #1 - 100% REMOVAL AND REPLACEMENT OF THE TRAFFIC COATING

REMOVE AND REPLACE 100% OF THE EXISTING TRAFFIC COATING USING A METHOD APPROPRIATE TO THE EXISTING CONCRETE CONDITIONS AND WHICH WILL RESULT IN A SURFACE THAT IS ACCEPTABLE FOR APPLICATION OF A NEW TRAFFIC COATING AS DIRECTED BY THE COATING MANUFACTURER. MAKE STRUCTURAL REPAIRS TO THE CONCRETE SLAB AS INDICATED ON THE DRAWINGS AND

ACCORDING TO THE REPAIR KEY NOTES BEFORE PREPARATION AND APPLICATION OF THE NEW TRAFFIC COATING. AFTER REPAIR AND PREPARATION AND CURING OF THE CONCRETE SURFACES, APPLY A NEW TRAFFIC

COATING OVER 100% OF THE EXPOSED CONCRETE SLAB SURFACE AND 100% OF THE CURBS AND WALKWAYS. APPLY TO THE HORIZONTAL AND VERTICAL SURFACES OF THE CURBS AND WALKWAYS. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER MARKINGS AFTER THE NEW TRAFFIC COATING IS APPLIED AND COMPLETELY CURED.

ALTERNATE #2 - 100% REMOVAL AND REPLACEMENT OF THE RAMP EXPANSION JOINTS SEE KEY NOTE 5. REMOVE AND REPLACE 100% OF THE EXISTING RAMP HORIZONTAL AND VERTICAL EXPANSION JOINTS AT ALL LEVELS. **NOTE:** REPLACEMENT OF EXPANSION JOINTS AT THE SKYWARD RAMPS BETWEEN LEVELS 'M' AND 'L' ARE TO BE CONSIDERED IN THE BASE BID.

BROWNING DAY MULLINS DIERDORF LEADERSHIP + DESIGN®

Browning Day Mullins Dierdorf Architects Architecture Landscape Architecture Planning Interior Design

626 North Illinois Street Indianapolis, Indiana 46204 Phone: (317) 635-5030 Website: www.bdmd.com

Delta Quad Holdings, LLC

Rau Construction Co. Construction Manager 9101 West 110th Street, Suite 150

Overland Park, Kansas 66210 Phone: (913) 642-6000 Website: www.website.com

Lawson Elser, Inc. Structural Engineer 650 East Carmel Drive, Suite 150

Carmel, Indiana 46032 Phone: (317) 574-5409 Website: www.lawsonelser.com

Hoss & Brown Engineers, Inc. MEP Engineer

11205 West 79th Street, Suite 102 Lenexa, Kansas 66214 Phone: (913) 362-9090 Website: www.h-be.com

SK Design Group, Inc. Civil Engineer 4600 College Boulevard, Suite 100

Overland Park, KS 66211 Phone: (913) 451-1818 Website: www.skdesigngroup.com

Matchline Design Group, LLC Interior Design 10300 North Central Expressway, Suite 335 Dallas, TX 75231

Phone: (972) 707-0568 Website: www.matchlinedesign.com

Garage Repair Plans dated January 25, 2019 are for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.

> CERTIFICATION GARAGE MAINTENANCE PACKAGE The Grand Reserve

925 Grand Boulevard Kansas City, MO 64198 Project No.: LEI #1851 Drawn By: Checked By: MjL Scale: See Drawing Issue Date: January 25, 2019 **REVISION SCHEDULE**

Rev. # Revision Description Issue Date









<u>NORTH</u>

GARAGE REPAIR KEY NOTES

SEE TYPICAL PATCH BOUNDARY, REBAR UNDERCUTTING AND PATCH DETAILS 1/S407-G, 2/S407-G, 3/S407-G

REPAIR (1) <u>SURFACE SLAB SPALL</u> - 1/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 1/S408-G. REMOVE THE EXISTING TRAFFIC COATING OVER THE SPALLED AREA. REMOVE SPALLED AND

DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED. **REPAIR** (2) <u>OVERHEAD SLAB SPALL</u> - 2/S408-G

EXAMINE THE UNDERSIDE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 2/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (3) <u>OVERHEAD BEAM SPALL</u> - 3/S408-G

EXAMINE THE UNDERSIDE OF THE BEAM WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF BEAM SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 3/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (4) <u>SLAB FULL DEPTH REPAIR</u> - 4/S408-G EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF FULL DEPTH SLAB HOLES.

REMOVE WATER, DEBRIS AND SPALLED OR DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. FILL THE FORM VOID WITH STYROFOAM TO CONTAIN THE PATCH MATERIAL AND FORM THE UNDERSIDE OF THE PATCH. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER THE REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

REPAIR (5) <u>EXPANSION JOINT REMOVAL AND REPLACEMENT</u> SEE ALTERNATE #2 - EXCEPT RAMPS BETWEEN LEVELS 'M' AND 'L'

REMOVE DAMAGED THE VERTICAL AND HORIZONTAL JOINT MATERIAL AND THOROUGHLY CLEAN THE JOINTS ACCORDING TO THE JOINT MATERIAL MANUFACTURER'S WRITTEN INSTRUCTIONS. ENSURE THAT THE CONCRETE ON EITHER SIDE AND AROUND THE JOINT IS SOUND, STABLE AND IN A CONDITION TO RECEIVE THE NEW JOINT MATERIAL. PLACE THE NEW JOINT MATERIAL ACCORDING TO THE JOINT MANUFACTURER'S WRITTEN INSTRUCTIONS, INCLUDING CLEANING, PRIMING, INSTALLATION AND CURING.

REPAIR (6) <u>NEW TRAFFIC COATING</u>

CLEAN THE DESIGNATED AREA OF EXISTING TRAFFIC COATING DOWN TO A STABLE CLEAN CONCRETE SURFACE. MAKE SLAB REPAIRS ACCORDING TO THE REPAIR KEY NOTES AS INDICATED ON THE DRAWINGS. APPLY PRIMER TO THE EXPOSED CONCRETE ACCORDING TO THE MANUFACTURER'S WRITTEN INSTRUCTIONS. APPLY THE LAYERS OF TRAFFIC COATING ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS AND THE SPECIFICATIONS. OVERLAP THE NEW COATING ONTO THE EXISTING COATING MIN OF 12" AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

GARAGE REPAIR GENERAL NOTES

- 1. THE GARAGE LAYOUT SHOWN ON THE REPAIR PLANS WAS TAKEN FROM EXISTING DRAWINGS AND MAY NOT ACCURATELY REFLECT AS-BUILT CONDITIONS. REPORT SIGNIFICANT VARIATIONS BETWEEN THE PLANS AND FIELD CONDITIONS TO THE ARCHITECT/ENGINEER. 2. CONTRACTOR TO EXAMINE THE ENTIRE GARAGE PRIOR TO MAKING REPAIRS AND BECOME
- FAMILIAR WITH EXISTING CONDITIONS. CONTRACTOR TO REPORT TO THE ARCHITECT/ENGINEER IF CONDITIONS ARE FOUND THAT MAY PREVENT THE WORK FROM BEING PERFORMED ACCORDING TO THE DRAWINGS AND SPECIFICATIONS. 3. CONTRACTOR TO COORDINATE THE WORK WITH THE PARKING GARAGE OWNER/OPERATOR
- REGARDING CLOSURE OF AREAS OF THE GARAGE AS REQUIRED TO MAKE THE REPAIRS. WORK SHALL BE PERFORMED ONLY AT NIGHT DURING OFF HOURS IF DESIGNATED BY THE OWNER/OPERATOR.
- 4. THE GENERAL FLOOR DECK FRAMING OF THIS PARKING GARAGE CONSISTS OF CAST-IN-PLACE, POST-TENSIONED SLABS AND BEAMS. THE SLABS ARE APPROXIMATELY 25" DEEP WITH FORM VOIDS THAT CREATE 6" WIDE CONCRETE JOISTS AT APPROXIMATELY 25" TO 26" ON CENTER. THESE JOISTS ARE REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. THE BEAMS ARE ALSO REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. UNDER NO CIRCUMSTANCES ARE THE P/T STRANDS TO BE DISTURBED, CUT, NICKED OR DAMAGED. IF DAMAGE TO P/T STRANDS IS DISCOVERED DURING THE COURSE OF THE PROJECT, STOP WORK IN THE AREA OF THE DAMAGED STRANDS AND REPORT TO THE ARCHITECT/ENGINEER IMMEDIATELY.
- 5. CONTRACTOR SHALL PROVIDE SHORING, DESIGNED BY A SHORING CONTRACTOR, FOR BEAM SPALL REPAIRS. SHORING SHALL EXTEND DOWN NO LESS THAN THREE LEVELS BELOW THE LEVEL OF THE BEAM UNDER REPAIR. 6. REFER TO THE WRITTEN SPECIFICATIONS AND MANUFACTURER'S WRITTEN INSTRUCTIONS FOR APPLICATION OF EACH REPAIR MATERIAL. A TECHNICAL REPRESENTATIVE FROM EACH OF THE
- REPAIR MATERIAL MANUFACTURER'S SHALL VISIT THE SITE AND PROVIDE SITE SPECIFIC INSTRUCTIONS. OBSERVE THE AMBIENT TEMPERATURE LIMITATIONS FOR APPLICATION OF EACH MATERIAL. 7. PROTECT THE GARAGE AND GARAGE CONTENTS THROUGHOUT THE COURSE OF THE WORK. DO NOT DAMAGE VEHICLES DURING THE COURSE OF THE WORK. SUCH DAMAGE SHALL BE THE
- RESPONSIBILITY OF THE CONTRACTOR. 8. FIELD LOCATE MECHANICAL EQUIPMENT, AIR INTAKE LOUVERS, EXHAUST LOUVERS OR OTHER HVAC EQUIPMENT THAT MAY BE DAMAGED BY DUST AND DEBRIS AND PROVIDE ADEQUATE FILTERS AND PROTECTION. DO NOT ALLOW DUST AND DEBRIS TO ENTER OCCUPIED SPACE IN THE BUILDINGS UNDER AND/OR ATTACHED TO THIS PARKING GARAGE. CONTAIN DUST AND DEBRIS FROM ESCAPING THE GARAGE AND INTO ADJACENT BUILDINGS OR THE PUBLIC ACCESS AROUND
- THE BUILDING. 9. THIS PARKING GARAGE IS SITUATED OVER BASEMENT LEVELS THAT ARE BELOW GRADE. PROTECT THESE BASEMENT LEVELS FROM DAMAGE AS A RESULT OF THE REPAIR WORK. CONTRACTOR SHALL BECOME FAMILIAR WITH THE BASEMENT LEVELS AND TAKE PRECAUTIONS AS NEEDED TO PROTECT THE SAME.
- 10. DO NOT USE EXCESSIVE WATER TO CLEAN, BLAST OR PRESSURE WASH THE GARAGE FLOORS THAT MAY LEAK INTO THE BASEMENTS BELOW. ENSURE THAT THE FLOOR DRAINS ARE CLEAN AND IN GOOD WORKING ORDER TO ENSURE THAT WATER, IF NEEDED, IS PROPERLY MANAGED. 11. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER FLOOR MARKINGS AS REQUIRED WHERE EXISTING MARKINGS ARE REMOVED OR DISTURBED BY THE SLAB REPAIR AND REPLACEMENT COATING WORK. OWNER/OPERATOR TO PROVIDE MARKINGS AS

<u>ALTERNATES</u>

ALTERNATE #1 - 100% REMOVAL AND REPLACEMENT OF THE TRAFFIC COATING

REQUIRED FOR OPERATION OF THE GARAGE.

REMOVE AND REPLACE 100% OF THE EXISTING TRAFFIC COATING USING A METHOD APPROPRIATE TO THE EXISTING CONCRETE CONDITIONS AND WHICH WILL RESULT IN A SURFACE THAT IS ACCEPTABLE FOR APPLICATION OF A NEW TRAFFIC COATING AS DIRECTED BY THE COATING MANUFACTURER. MAKE STRUCTURAL REPAIRS TO THE CONCRETE SLAB AS INDICATED ON THE DRAWINGS AND ACCORDING TO THE REPAIR KEY NOTES BEFORE PREPARATION AND APPLICATION OF THE NEW TRAFFIC COATING.

AFTER REPAIR AND PREPARATION AND CURING OF THE CONCRETE SURFACES, APPLY A NEW TRAFFIC COATING OVER 100% OF THE EXPOSED CONCRETE SLAB SURFACE AND 100% OF THE CURBS AND WALKWAYS. APPLY TO THE HORIZONTAL AND VERTICAL SURFACES OF THE CURBS AND WALKWAYS. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER MARKINGS AFTER THE NEW TRAFFIC COATING IS APPLIED AND COMPLETELY CURED.

ALTERNATE #2 - 100% REMOVAL AND REPLACEMENT OF THE RAMP EXPANSION JOINTS SEE KEY NOTE 5. REMOVE AND REPLACE 100% OF THE EXISTING RAMP HORIZONTAL AND VERTICAL EXPANSION JOINTS AT ALL LEVELS. **NOTE:** REPLACEMENT OF EXPANSION JOINTS AT THE SKYWARD RAMPS BETWEEN LEVELS 'M' AND 'L' ARE TO BE CONSIDERED IN THE BASE BID.

BROWNING DAY MULLINS DIERDORF LEADERSHIP + DESIGN® Browning Day Mullins Dierdorf Architects Architecture Landscape Architecture

Planning Interior Design 626 North Illinois Street Indianapolis, Indiana 46204 Phone: (317) 635-5030 Website: www.bdmd.com

Delta Quad Holdings, LLC

Rau Construction Co. Construction Manager 9101 West 110th Street, Suite 150 Overland Park, Kansas 66210

Phone: (913) 642-6000 Website: www.website.com

Lawson Elser, Inc. Structural Engineer 650 East Carmel Drive, Suite 150 Carmel, Indiana 46032

Phone: (317) 574-5409 Website: www.lawsonelser.com

Hoss & Brown Engineers, Inc. MEP Engineer

11205 West 79th Street, Suite 102 Lenexa, Kansas 66214 Phone: (913) 362-9090 Website: www.h-be.com

SK Design Group, Inc. Civil Engineer 4600 College Boulevard, Suite 100 Overland Park, KS 66211

Phone: (913) 451-1818 Website: www.skdesigngroup.com

Matchline Design Group, LLC Interior Design 10300 North Central Expressway, Suite 335 Dallas, TX 75231

Phone: (972) 707-0568 Website: www.matchlinedesign.com


Garage Repair Plans dated January 25, 2019 are for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.


> CERTIFICATION GARAGE MAINTENANCE PACKAGE

The Grand Reserve

925 Grand Boulevard Kansas City, MO 64198				
Project No.: LEI #1851 Drawn By: Checked By: MjL Scale: See Drawing Issue Date: January 25, 2019				
REVISION SCHEDULE				
Rev. # F	Revision Description	Issue Date		









GARAGE REPAIR KEY NOTES

SEE TYPICAL PATCH BOUNDARY, REBAR UNDERCUTTING AND PATCH DETAILS 1/S407-G, 2/S407-G, 3/S407-G

REPAIR (1) <u>SURFACE SLAB SPALL</u> - 1/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 1/S408-G.

REMOVE THE EXISTING TRAFFIC COATING OVER THE SPALLED AREA. REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE, BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF, DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED. **REPAIR** (2) <u>OVERHEAD SLAB SPALL</u> - 2/S408-G

EXAMINE THE UNDERSIDE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 2/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (3) <u>OVERHEAD BEAM SPALL</u> - 3/S408-G

EXAMINE THE UNDERSIDE OF THE BEAM WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF BEAM SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 3/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (4) <u>SLAB FULL DEPTH REPAIR</u> - 4/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF FULL DEPTH SLAB HOLES. REMOVE WATER, DEBRIS AND SPALLED OR DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND

PREPARE THE EXPOSED CONCRETE SURFACE. FILL THE FORM VOID WITH STYROFOAM TO CONTAIN THE PATCH MATERIAL AND FORM THE UNDERSIDE OF THE PATCH. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER THE REPAIRS ARE COMPLETED AND FULLY CURED. PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

 REPAIR (5)
 EXPANSION JOINT REMOVAL AND REPLACEMENT

 SEE ALTERNATE #2 - EXCEPT RAMPS BETWEEN LEVELS 'M' AND 'L'

REMOVE DAMAGED THE VERTICAL AND HORIZONTAL JOINT MATERIAL AND THOROUGHLY CLEAN THE JOINTS ACCORDING TO THE JOINT MATERIAL MANUFACTURER'S WRITTEN INSTRUCTIONS. ENSURE THAT THE CONCRETE ON EITHER SIDE AND AROUND THE JOINT IS SOUND, STABLE AND IN A CONDITION TO RECEIVE THE NEW JOINT MATERIAL. PLACE THE NEW JOINT MATERIAL ACCORDING TO THE JOINT MANUFACTURER'S WRITTEN INSTRUCTIONS, INCLUDING CLEANING, PRIMING, INSTALLATION AND CURING.

REPAIR (6) <u>NEW TRAFFIC COATING</u>

<u>NORTH</u>

CLEAN THE DESIGNATED AREA OF EXISTING TRAFFIC COATING DOWN TO A STABLE CLEAN CONCRETE SURFACE. MAKE SLAB REPAIRS ACCORDING TO THE REPAIR KEY NOTES AS INDICATED ON THE DRAWINGS. APPLY PRIMER TO THE EXPOSED CONCRETE ACCORDING TO THE MANUFACTURER'S WRITTEN INSTRUCTIONS. APPLY THE LAYERS OF TRAFFIC COATING ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS AND THE SPECIFICATIONS. OVERLAP THE NEW COATING ONTO THE EXISTING COATING MIN OF 12" AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

GARAGE REPAIR GENERAL NOTES

- 1. THE GARAGE LAYOUT SHOWN ON THE REPAIR PLANS WAS TAKEN FROM EXISTING DRAWINGS AND MAY NOT ACCURATELY REFLECT AS-BUILT CONDITIONS. REPORT SIGNIFICANT VARIATIONS BETWEEN THE PLANS AND FIELD CONDITIONS TO THE ARCHITECT/ENGINEER. 2. CONTRACTOR TO EXAMINE THE ENTIRE GARAGE PRIOR TO MAKING REPAIRS AND BECOME
- FAMILIAR WITH EXISTING CONDITIONS. CONTRACTOR TO REPORT TO THE ARCHITECT/ENGINEER IF CONDITIONS ARE FOUND THAT MAY PREVENT THE WORK FROM BEING PERFORMED ACCORDING TO THE DRAWINGS AND SPECIFICATIONS. 3. CONTRACTOR TO COORDINATE THE WORK WITH THE PARKING GARAGE OWNER/OPERATOR
- REGARDING CLOSURE OF AREAS OF THE GARAGE AS REQUIRED TO MAKE THE REPAIRS. WORK SHALL BE PERFORMED ONLY AT NIGHT DURING OFF HOURS IF DESIGNATED BY THE OWNER/OPERATOR. 4. THE GENERAL FLOOR DECK FRAMING OF THIS PARKING GARAGE CONSISTS OF CAST-IN-PLACE,
- POST-TENSIONED SLABS AND BEAMS. THE SLABS ARE APPROXIMATELY 25" DEEP WITH FORM VOIDS THAT CREATE 6" WIDE CONCRETE JOISTS AT APPROXIMATELY 25" TO 26" ON CENTER. THESE JOISTS ARE REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. THE BEAMS ARE ALSO REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. UNDER NO CIRCUMSTANCES ARE THE P/T STRANDS TO BE DISTURBED, CUT, NICKED OR DAMAGED. IF DAMAGE TO P/T STRANDS IS DISCOVERED DURING THE COURSE OF THE PROJECT, STOP WORK IN THE AREA OF THE DAMAGED
- STRANDS AND REPORT TO THE ARCHITECT/ENGINEER IMMEDIATELY. 5. CONTRACTOR SHALL PROVIDE SHORING, DESIGNED BY A SHORING CONTRACTOR, FOR BEAM SPALL REPAIRS. SHORING SHALL EXTEND DOWN NO LESS THAN THREE LEVELS BELOW THE LEVEL OF THE BEAM UNDER REPAIR.
- 6. REFER TO THE WRITTEN SPECIFICATIONS AND MANUFACTURER'S WRITTEN INSTRUCTIONS FOR APPLICATION OF EACH REPAIR MATERIAL. A TECHNICAL REPRESENTATIVE FROM EACH OF THE REPAIR MATERIAL MANUFACTURER'S SHALL VISIT THE SITE AND PROVIDE SITE SPECIFIC INSTRUCTIONS. OBSERVE THE AMBIENT TEMPERATURE LIMITATIONS FOR APPLICATION OF EACH
- MATERIAL. 7. PROTECT THE GARAGE AND GARAGE CONTENTS THROUGHOUT THE COURSE OF THE WORK. DO NOT DAMAGE VEHICLES DURING THE COURSE OF THE WORK. SUCH DAMAGE SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR.
- 8. FIELD LOCATE MECHANICAL EQUIPMENT, AIR INTAKE LOUVERS, EXHAUST LOUVERS OR OTHER HVAC EQUIPMENT THAT MAY BE DAMAGED BY DUST AND DEBRIS AND PROVIDE ADEQUATE FILTERS AND PROTECTION. DO NOT ALLOW DUST AND DEBRIS TO ENTER OCCUPIED SPACE IN THE BUILDINGS UNDER AND/OR ATTACHED TO THIS PARKING GARAGE. CONTAIN DUST AND DEBRIS FROM ESCAPING THE GARAGE AND INTO ADJACENT BUILDINGS OR THE PUBLIC ACCESS AROUND THE BUILDING.
- 9. THIS PARKING GARAGE IS SITUATED OVER BASEMENT LEVELS THAT ARE BELOW GRADE. PROTECT THESE BASEMENT LEVELS FROM DAMAGE AS A RESULT OF THE REPAIR WORK. CONTRACTOR SHALL BECOME FAMILIAR WITH THE BASEMENT LEVELS AND TAKE PRECAUTIONS AS NEEDED TO PROTECT THE SAME.
- 10. DO NOT USE EXCESSIVE WATER TO CLEAN, BLAST OR PRESSURE WASH THE GARAGE FLOORS THAT MAY LEAK INTO THE BASEMENTS BELOW. ENSURE THAT THE FLOOR DRAINS ARE CLEAN AND IN GOOD WORKING ORDER TO ENSURE THAT WATER. IF NEEDED, IS PROPERLY MANAGED. 11. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER FLOOR MARKINGS AS REQUIRED WHERE EXISTING MARKINGS ARE REMOVED OR DISTURBED BY THE SLAB
- REPAIR AND REPLACEMENT COATING WORK. OWNER/OPERATOR TO PROVIDE MARKINGS AS REQUIRED FOR OPERATION OF THE GARAGE.

ALTERNATES

TRAFFIC COATING.

ALTERNATE #1 - 100% REMOVAL AND REPLACEMENT OF THE TRAFFIC COATING

REMOVE AND REPLACE 100% OF THE EXISTING TRAFFIC COATING USING A METHOD APPROPRIATE TO THE EXISTING CONCRETE CONDITIONS AND WHICH WILL RESULT IN A SURFACE THAT IS ACCEPTABLE FOR APPLICATION OF A NEW TRAFFIC COATING AS DIRECTED BY THE COATING MANUFACTURER. MAKE STRUCTURAL REPAIRS TO THE CONCRETE SLAB AS INDICATED ON THE DRAWINGS AND ACCORDING TO THE REPAIR KEY NOTES BEFORE PREPARATION AND APPLICATION OF THE NEW

AFTER REPAIR AND PREPARATION AND CURING OF THE CONCRETE SURFACES, APPLY A NEW TRAFFIC COATING OVER 100% OF THE EXPOSED CONCRETE SLAB SURFACE AND 100% OF THE CURBS AND WALKWAYS. APPLY TO THE HORIZONTAL AND VERTICAL SURFACES OF THE CURBS AND WALKWAYS. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER MARKINGS AFTER THE NEW TRAFFIC COATING IS APPLIED AND COMPLETELY CURED.

ALTERNATE #2 - 100% REMOVAL AND REPLACEMENT OF THE RAMP EXPANSION JOINTS

SEE KEY NOTE 5. REMOVE AND REPLACE 100% OF THE EXISTING RAMP HORIZONTAL AND VERTICAL EXPANSION JOINTS AT ALL LEVELS. NOTE: REPLACEMENT OF EXPANSION JOINTS AT THE SKYWARD RAMPS BETWEEN LEVELS 'M' AND 'L' ARE TO BE CONSIDERED IN THE BASE BID.

BROWNING DAY MULLINS DIERDORF LEADERSHIP + DESIGN®

Browning Day Mullins Dierdorf Architects Architecture Landscape Architecture Plannin Interior Design

626 North Illinois Street Indianapolis, Indiana 46204 Phone: (317) 635-5030 Website: www.bdmd.com

Delta Quad Holdings, LLC

Rau Construction Co. Construction Manager 9101 West 110th Street, Suite 150

Overland Park, Kansas 66210 Phone: (913) 642-6000 Website: www.website.com

Lawson Elser, Inc. Structural Engineer

650 East Carmel Drive, Suite 150 Carmel, Indiana 46032 Phone: (317) 574-5409 Website: www.lawsonelser.com

Hoss & Brown Engineers, Inc. MEP Engineer

11205 West 79th Street, Suite 102 Lenexa, Kansas 66214 Phone: (913) 362-9090 Website: www.h-be.com

SK Design Group, Inc. Civil Engineer 4600 College Boulevard, Suite 100

Overland Park, KS 66211 Phone: (913) 451-1818 Website: www.skdesigngroup.com

Matchline Design Group, LLC Interior Design 10300 North Central Expressway, Suite 335 Dallas, TX 75231


Phone: (972) 707-0568 Website: www.matchlinedesign.com


Garage Repair Plans dated January 25, 2019 are for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.

> CERTIFICATION GARAGE MAINTENANCE PACKAGE

The Grand Reserve








I

I

SURFACE REPAIRS LEVEL K & L 3/32" = 1'-0"

OVERHEAD REPAIRS LEVEL K 3/32" = 1'-0"

I





GARAGE REPAIR KEY NOTES

SEE TYPICAL PATCH BOUNDARY, REBAR UNDERCUTTING AND PATCH DETAILS 1/S407-G, 2/S407-G, 3/S407-G

REPAIR (1) <u>SURFACE SLAB SPALL</u> - 1/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 1/S408-G.

REMOVE THE EXISTING TRAFFIC COATING OVER THE SPALLED AREA. REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED. REPAIR (2) OVERHEAD SLAB SPALL - 2/S408-G

EXAMINE THE UNDERSIDE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 2/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (3) <u>OVERHEAD BEAM SPALL</u> - 3/S408-G

EXAMINE THE UNDERSIDE OF THE BEAM WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF BEAM SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 3/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (4) <u>SLAB FULL DEPTH REPAIR</u> - 4/S408-G EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF FULL

DEPTH SLAB HOLES. REMOVE WATER, DEBRIS AND SPALLED OR DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. FILL THE FORM VOID WITH STYROFOAM TO CONTAIN THE PATCH MATERIAL AND FORM THE UNDERSIDE OF THE PATCH. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING

TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. AFTER THE REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

REPAIR (5) EXPANSION JOINT REMOVAL AND REPLACEMENT SEE ALTERNATE #2 - EXCEPT RAMPS BETWEEN LEVELS 'M' AND 'L'

REMOVE DAMAGED THE VERTICAL AND HORIZONTAL JOINT MATERIAL AND THOROUGHLY CLEAN THE JOINTS ACCORDING TO THE JOINT MATERIAL MANUFACTURER'S WRITTEN INSTRUCTIONS. ENSURE THAT THE CONCRETE ON EITHER SIDE AND AROUND THE JOINT IS SOUND, STABLE AND IN A CONDITION TO RECEIVE THE NEW JOINT MATERIAL. PLACE THE NEW JOINT MATERIAL ACCORDING TO THE JOINT MANUFACTURER'S WRITTEN INSTRUCTIONS, INCLUDING CLEANING, PRIMING, INSTALLATION AND CURING.

REPAIR 6 <u>NEW TRAFFIC COATING</u>

CLEAN THE DESIGNATED AREA OF EXISTING TRAFFIC COATING DOWN TO A STABLE CLEAN CONCRETE SURFACE. MAKE SLAB REPAIRS ACCORDING TO THE REPAIR KEY NOTES AS INDICATED ON THE DRAWINGS. APPLY PRIMER TO THE EXPOSED CONCRETE ACCORDING TO THE MANUFACTURER'S WRITTEN INSTRUCTIONS. APPLY THE LAYERS OF TRAFFIC COATING ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS AND THE SPECIFICATIONS. OVERLAP THE NEW COATING ONTO THE EXISTING COATING MIN OF 12" AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

GARAGE REPAIR GENERAL NOTES

- 1. THE GARAGE LAYOUT SHOWN ON THE REPAIR PLANS WAS TAKEN FROM EXISTING DRAWINGS AND MAY NOT ACCURATELY REFLECT AS-BUILT CONDITIONS. REPORT SIGNIFICANT VARIATIONS BETWEEN THE PLANS AND FIELD CONDITIONS TO THE ARCHITECT/ENGINEER. 2. CONTRACTOR TO EXAMINE THE ENTIRE GARAGE PRIOR TO MAKING REPAIRS AND BECOME
- FAMILIAR WITH EXISTING CONDITIONS. CONTRACTOR TO REPORT TO THE ARCHITECT/ENGINEER IF CONDITIONS ARE FOUND THAT MAY PREVENT THE WORK FROM BEING PERFORMED ACCORDING TO THE DRAWINGS AND SPECIFICATIONS. 3. CONTRACTOR TO COORDINATE THE WORK WITH THE PARKING GARAGE OWNER/OPERATOR
- REGARDING CLOSURE OF AREAS OF THE GARAGE AS REQUIRED TO MAKE THE REPAIRS. WORK SHALL BE PERFORMED ONLY AT NIGHT DURING OFF HOURS IF DESIGNATED BY THE OWNER/OPERATOR. 4. THE GENERAL FLOOR DECK FRAMING OF THIS PARKING GARAGE CONSISTS OF CAST-IN-PLACE,
- POST-TENSIONED SLABS AND BEAMS. THE SLABS ARE APPROXIMATELY 25" DEEP WITH FORM VOIDS THAT CREATE 6" WIDE CONCRETE JOISTS AT APPROXIMATELY 25" TO 26" ON CENTER. THESE JOISTS ARE REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. THE BEAMS ARE ALSO REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. UNDER NO CIRCUMSTANCES ARE THE P/T STRANDS TO BE DISTURBED, CUT, NICKED OR DAMAGED. IF DAMAGE TO P/T STRANDS IS DISCOVERED DURING THE COURSE OF THE PROJECT, STOP WORK IN THE AREA OF THE DAMAGED
- STRANDS AND REPORT TO THE ARCHITECT/ENGINEER IMMEDIATELY. 5. CONTRACTOR SHALL PROVIDE SHORING, DESIGNED BY A SHORING CONTRACTOR, FOR BEAM SPALL REPAIRS. SHORING SHALL EXTEND DOWN NO LESS THAN THREE LEVELS BELOW THE LEVEL OF THE BEAM UNDER REPAIR. 6. REFER TO THE WRITTEN SPECIFICATIONS AND MANUFACTURER'S WRITTEN INSTRUCTIONS FOR
- APPLICATION OF EACH REPAIR MATERIAL. A TECHNICAL REPRESENTATIVE FROM EACH OF THE REPAIR MATERIAL MANUFACTURER'S SHALL VISIT THE SITE AND PROVIDE SITE SPECIFIC INSTRUCTIONS. OBSERVE THE AMBIENT TEMPERATURE LIMITATIONS FOR APPLICATION OF EACH MATERIAL.
- 7. PROTECT THE GARAGE AND GARAGE CONTENTS THROUGHOUT THE COURSE OF THE WORK. DO NOT DAMAGE VEHICLES DURING THE COURSE OF THE WORK. SUCH DAMAGE SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR. 8. FIELD LOCATE MECHANICAL EQUIPMENT, AIR INTAKE LOUVERS, EXHAUST LOUVERS OR OTHER
- HVAC EQUIPMENT THAT MAY BE DAMAGED BY DUST AND DEBRIS AND PROVIDE ADEQUATE FILTERS AND PROTECTION. DO NOT ALLOW DUST AND DEBRIS TO ENTER OCCUPIED SPACE IN THE BUILDINGS UNDER AND/OR ATTACHED TO THIS PARKING GARAGE. CONTAIN DUST AND DEBRIS FROM ESCAPING THE GARAGE AND INTO ADJACENT BUILDINGS OR THE PUBLIC ACCESS AROUND THE BUILDING.
- 9. THIS PARKING GARAGE IS SITUATED OVER BASEMENT LEVELS THAT ARE BELOW GRADE. PROTECT THESE BASEMENT LEVELS FROM DAMAGE AS A RESULT OF THE REPAIR WORK. CONTRACTOR SHALL BECOME FAMILIAR WITH THE BASEMENT LEVELS AND TAKE PRECAUTIONS AS NEEDED TO PROTECT THE SAME. 10. DO NOT USE EXCESSIVE WATER TO CLEAN, BLAST OR PRESSURE WASH THE GARAGE FLOORS
- THAT MAY LEAK INTO THE BASEMENTS BELOW. ENSURE THAT THE FLOOR DRAINS ARE CLEAN AND IN GOOD WORKING ORDER TO ENSURE THAT WATER, IF NEEDED, IS PROPERLY MANAGED. 11. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER FLOOR MARKINGS AS REQUIRED WHERE EXISTING MARKINGS ARE REMOVED OR DISTURBED BY THE SLAB

REPAIR AND REPLACEMENT COATING WORK. OWNER/OPERATOR TO PROVIDE MARKINGS AS REQUIRED FOR OPERATION OF THE GARAGE.

<u>ALTERNATES</u>

TRAFFIC COATING.

ALTERNATE #1 - 100% REMOVAL AND REPLACEMENT OF THE TRAFFIC COATING REMOVE AND REPLACE 100% OF THE EXISTING TRAFFIC COATING USING A METHOD APPROPRIATE TO THE EXISTING CONCRETE CONDITIONS AND WHICH WILL RESULT IN A SURFACE THAT IS ACCEPTABLE FOR APPLICATION OF A NEW TRAFFIC COATING AS DIRECTED BY THE COATING MANUFACTURER. MAKE STRUCTURAL REPAIRS TO THE CONCRETE SLAB AS INDICATED ON THE DRAWINGS AND ACCORDING TO THE REPAIR KEY NOTES BEFORE PREPARATION AND APPLICATION OF THE NEW

AFTER REPAIR AND PREPARATION AND CURING OF THE CONCRETE SURFACES, APPLY A NEW TRAFFIC COATING OVER 100% OF THE EXPOSED CONCRETE SLAB SURFACE AND 100% OF THE CURBS AND WALKWAYS. APPLY TO THE HORIZONTAL AND VERTICAL SURFACES OF THE CURBS AND WALKWAYS. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER MARKINGS AFTER THE NEW TRAFFIC COATING IS APPLIED AND COMPLETELY CURED.

ALTERNATE #2 - 100% REMOVAL AND REPLACEMENT OF THE RAMP EXPANSION JOINTS SEE KEY NOTE 5. REMOVE AND REPLACE 100% OF THE EXISTING RAMP HORIZONTAL AND VERTICAL EXPANSION JOINTS AT ALL LEVELS. NOTE; REPLACEMENT OF EXPANSION JOINTS AT THE SKYWARD RAMPS BETWEEN LEVELS 'M' AND 'L' ARE TO BE CONSIDERED IN THE BASE BID.





I.

I

BROWNING DAY MULLINS DIERDORF LEADERSHIP + DESIGN®

Browning Day Mullins Dierdorf Architects Architecture Landscape Architecture Plannin Interior Design

626 North Illinois Street Indianapolis, Indiana 46204 Phone: (317) 635-5030 Website: www.bdmd.com

Delta Quad Holdings, LLC

Rau Construction Co. Construction Manager 9101 West 110th Street, Suite 150

Overland Park, Kansas 66210 Phone: (913) 642-6000 Website: www.website.com

Lawson Elser, Inc. Structural Engineer 650 East Carmel Drive, Suite 150

Carmel, Indiana 46032 Phone: (317) 574-5409 Website: www.lawsonelser.com

Hoss & Brown Engineers, Inc. MEP Engineer

11205 West 79th Street, Suite 102 Lenexa, Kansas 66214 Phone: (913) 362-9090 Website: www.h-be.com

SK Design Group, Inc. Civil Engineer 4600 College Boulevard, Suite 100

Overland Park, KS 66211 Phone: (913) 451-1818 Website: www.skdesigngroup.com

Matchline Design Group, LLC Interior Design 10300 North Central Expressway, Suite 335 Dallas, TX 75231

Phone: (972) 707-0568 Website: www.matchlinedesign.com


Garage Repair Plans dated January 25, 2019 are for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.


> CERTIFICATION GARAGE MAINTENANCE PACKAGE


The Grand Reserve

925 Grand Boulevard Kansas City, MO 64198				
Project No.: LEI #1851 Drawn By: Checked By: MjL Scale: See Drawing Issue Date: January 25, 2019				
REVISION SCHEDULE				
Rev. #	Revision Description	Issue Date		











L

SURFACE REPAIRS LEVEL M 3/32" = 1'-0"



2

Í



EXPOSING & UNDERCUTTING OF REINFORCING STEEL N.T.S.

I



GARAGE REPAIR KEY NOTES

SEE TYPICAL PATCH BOUNDARY, REBAR UNDERCUTTING AND PATCH DETAILS 1/S407-G, 2/S407-G, 3/S407-G

REPAIR (1) <u>SURFACE SLAB SPALL</u> - 1/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 1/S408-G.

REMOVE THE EXISTING TRAFFIC COATING OVER THE SPALLED AREA. REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. AFTER REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA

WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED. **REPAIR** (2) <u>OVERHEAD SLAB SPALL</u> - 2/S408-G

EXAMINE THE UNDERSIDE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF SLAB SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 2/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (3) <u>OVERHEAD BEAM SPALL</u> - 3/S408-G

EXAMINE THE UNDERSIDE OF THE BEAM WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF BEAM SPALLING. DETERMINE IF THE SPALL IS SHALLOW OR DEEP AS DEFINED ON 3/S408-G.

REMOVE SPALLED AND DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. BLAST AND PREPARE THE EXPOSED REINFORCING BARS DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE ABOVE THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS. REPAIR INCIDENTAL DAMAGE TO THE STRAND SHEATHING WITH WATERPROOF TAPE DESIGNED SPECIFICALLY FOR SHEATHING REPAIR AND APPLY ACCORDING TO MANUFACTURER'S INSTRUCTIONS.

AFTER REPAIRS ARE COMPLETED AND FULLY CURED, REPAINT THE REPAIR AREA WITH PAINT TO MATCH EXISTING IN COLOR AND TEXTURE. APPLY PRIMER AND FINISH COAT AS REQUIRED FOR A COMPLETE COATING.

REPAIR (4) <u>SLAB FULL DEPTH REPAIR</u> - 4/S408-G

EXAMINE THE SURFACE OF THE SLAB WITHIN THE DESIGNATED AREA AND IDENTIFY INSTANCES OF FULL DEPTH SLAB HOLES.

REMOVE WATER, DEBRIS AND SPALLED OR DELAMINATED CONCRETE TO A SOUND SUBSTRATE AND PREPARE THE EXPOSED CONCRETE SURFACE. FILL THE FORM VOID WITH STYROFOAM TO CONTAIN THE PATCH MATERIAL AND FORM THE UNDERSIDE OF THE PATCH. BLAST AND PREPARE THE EXPOSED REINFORCING BARS AND WWF. DO NOT DISTURB POST-TENSIONING STRANDS OR REMOVE CONCRETE BELOW THE STRANDS. APPLY PRIMER TO THE CONCRETE SURFACE AND ANTI-CORROSION COATING TO THE REBAR. APPLY THE SPECIFIED PATCH MATERIAL TO THE PREPARED AREA ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS.

AFTER THE REPAIRS ARE COMPLETED AND FULLY CURED, PREPARE AND COAT THE NEWLY PATCHED AREA WITH NEW TRAFFIC COATING WITH A MIN 12" OVERLAP ONTO THE EXISTING COATING AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

REPAIR (5) EXPANSION JOINT REMOVAL AND REPLACEMENT SEE ALTERNATE #2 - EXCEPT RAMPS BETWEEN LEVELS 'M' AND 'L'

REMOVE DAMAGED THE VERTICAL AND HORIZONTAL JOINT MATERIAL AND THOROUGHLY CLEAN THE JOINTS ACCORDING TO THE JOINT MATERIAL MANUFACTURER'S WRITTEN INSTRUCTIONS. ENSURE THAT THE CONCRETE ON EITHER SIDE AND AROUND THE JOINT IS SOUND, STABLE AND IN A CONDITION TO RECEIVE THE NEW JOINT MATERIAL. PLACE THE NEW JOINT MATERIAL ACCORDING TO THE JOINT MANUFACTURER'S WRITTEN INSTRUCTIONS, INCLUDING CLEANING, PRIMING, INSTALLATION AND CURING.

REPAIR (6) <u>NEW TRAFFIC COATING</u>

CLEAN THE DESIGNATED AREA OF EXISTING TRAFFIC COATING DOWN TO A STABLE CLEAN CONCRETE SURFACE. MAKE SLAB REPAIRS ACCORDING TO THE REPAIR KEY NOTES AS INDICATED ON THE DRAWINGS. APPLY PRIMER TO THE EXPOSED CONCRETE ACCORDING TO THE MANUFACTURER'S WRITTEN INSTRUCTIONS. APPLY THE LAYERS OF TRAFFIC COATING ACCORDING TO THE MANUFACTURE'S WRITTEN INSTRUCTIONS AND THE SPECIFICATIONS. OVERLAP THE NEW COATING ONTO THE EXISTING COATING MIN OF 12" AROUND THE PERIMETER OF THE REPAIR AREA. RE-PAINT STRIPING AND/OR TRAFFIC MARKINGS AS REQUIRED.

GARAGE REPAIR GENERAL NOTES

- 1. THE GARAGE LAYOUT SHOWN ON THE REPAIR PLANS WAS TAKEN FROM EXISTING DRAWINGS AND MAY NOT ACCURATELY REFLECT AS-BUILT CONDITIONS. REPORT SIGNIFICANT VARIATIONS BETWEEN THE PLANS AND FIELD CONDITIONS TO THE ARCHITECT/ENGINEER. 2. CONTRACTOR TO EXAMINE THE ENTIRE GARAGE PRIOR TO MAKING REPAIRS AND BECOME
- FAMILIAR WITH EXISTING CONDITIONS. CONTRACTOR TO REPORT TO THE ARCHITECT/ENGINEER IF CONDITIONS ARE FOUND THAT MAY PREVENT THE WORK FROM BEING PERFORMED ACCORDING TO THE DRAWINGS AND SPECIFICATIONS. 3. CONTRACTOR TO COORDINATE THE WORK WITH THE PARKING GARAGE OWNER/OPERATOR
- REGARDING CLOSURE OF AREAS OF THE GARAGE AS REQUIRED TO MAKE THE REPAIRS. WORK SHALL BE PERFORMED ONLY AT NIGHT DURING OFF HOURS IF DESIGNATED BY THE OWNER/OPERATOR. 4. THE GENERAL FLOOR DECK FRAMING OF THIS PARKING GARAGE CONSISTS OF CAST-IN-PLACE,
- POST-TENSIONED SLABS AND BEAMS. THE SLABS ARE APPROXIMATELY 25" DEEP WITH FORM VOIDS THAT CREATE 6" WIDE CONCRETE JOISTS AT APPROXIMATELY 25" TO 26" ON CENTER. THESE JOISTS ARE REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. THE BEAMS ARE ALSO REINFORCED WITH CONVENTIONAL REBAR AND P/T STRANDS. UNDER NO CIRCUMSTANCES ARE THE P/T STRANDS TO BE DISTURBED, CUT, NICKED OR DAMAGED. IF DAMAGE TO P/T STRANDS IS DISCOVERED DURING THE COURSE OF THE PROJECT, STOP WORK IN THE AREA OF THE DAMAGED STRANDS AND REPORT TO THE ARCHITECT/ENGINEER IMMEDIATELY.
- 5. CONTRACTOR SHALL PROVIDE SHORING, DESIGNED BY A SHORING CONTRACTOR, FOR BEAM SPALL REPAIRS. SHORING SHALL EXTEND DOWN NO LESS THAN THREE LEVELS BELOW THE LEVEL OF THE BEAM UNDER REPAIR. 6. REFER TO THE WRITTEN SPECIFICATIONS AND MANUFACTURER'S WRITTEN INSTRUCTIONS FOR APPLICATION OF EACH REPAIR MATERIAL. A TECHNICAL REPRESENTATIVE FROM EACH OF THE
- REPAIR MATERIAL MANUFACTURER'S SHALL VISIT THE SITE AND PROVIDE SITE SPECIFIC INSTRUCTIONS. OBSERVE THE AMBIENT TEMPERATURE LIMITATIONS FOR APPLICATION OF EACH MATERIAL. 7. PROTECT THE GARAGE AND GARAGE CONTENTS THROUGHOUT THE COURSE OF THE WORK. DO
- NOT DAMAGE VEHICLES DURING THE COURSE OF THE WORK. SUCH DAMAGE SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR. 8. FIELD LOCATE MECHANICAL EQUIPMENT, AIR INTAKE LOUVERS, EXHAUST LOUVERS OR OTHER HVAC EQUIPMENT THAT MAY BE DAMAGED BY DUST AND DEBRIS AND PROVIDE ADEQUATE FILTERS AND PROTECTION. DO NOT ALLOW DUST AND DEBRIS TO ENTER OCCUPIED SPACE IN THE BUILDINGS UNDER AND/OR ATTACHED TO THIS PARKING GARAGE. CONTAIN DUST AND DEBRIS
- FROM ESCAPING THE GARAGE AND INTO ADJACENT BUILDINGS OR THE PUBLIC ACCESS AROUND THE BUILDING. 9. THIS PARKING GARAGE IS SITUATED OVER BASEMENT LEVELS THAT ARE BELOW GRADE. PROTECT THESE BASEMENT LEVELS FROM DAMAGE AS A RESULT OF THE REPAIR WORK. CONTRACTOR
- SHALL BECOME FAMILIAR WITH THE BASEMENT LEVELS AND TAKE PRECAUTIONS AS NEEDED TO PROTECT THE SAME. 10. DO NOT USE EXCESSIVE WATER TO CLEAN, BLAST OR PRESSURE WASH THE GARAGE FLOORS THAT MAY LEAK INTO THE BASEMENTS BELOW. ENSURE THAT THE FLOOR DRAINS ARE CLEAN AND IN GOOD WORKING ORDER TO ENSURE THAT WATER, IF NEEDED, IS PROPERLY MANAGED.
- 11. REPAINT STRIPING, DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER FLOOR MARKINGS AS REQUIRED WHERE EXISTING MARKINGS ARE REMOVED OR DISTURBED BY THE SLAB REPAIR AND REPLACEMENT COATING WORK. OWNER/OPERATOR TO PROVIDE MARKINGS AS REQUIRED FOR OPERATION OF THE GARAGE.

ALTERNATES

1

ALTERNATE #1 - 100% REMOVAL AND REPLACEMENT OF THE TRAFFIC COATING REMOVE AND REPLACE 100% OF THE EXISTING TRAFFIC COATING USING A METHOD APPROPRIATE TO THE EXISTING CONCRETE CONDITIONS AND WHICH WILL RESULT IN A SURFACE THAT IS ACCEPTABLE

MAKE STRUCTURAL REPAIRS TO THE CONCRETE SLAB AS INDICATED ON THE DRAWINGS AND ACCORDING TO THE REPAIR KEY NOTES BEFORE PREPARATION AND APPLICATION OF THE NEW TRAFFIC COATING.

FOR APPLICATION OF A NEW TRAFFIC COATING AS DIRECTED BY THE COATING MANUFACTURER.

AFTER REPAIR AND PREPARATION AND CURING OF THE CONCRETE SURFACES, APPLY A NEW TRAFFIC COATING OVER 100% OF THE EXPOSED CONCRETE SLAB SURFACE AND 100% OF THE CURBS AND WALKWAYS. APPLY TO THE HORIZONTAL AND VERTICAL SURFACES OF THE CURBS AND WALKWAYS. REPAINT STRIPING. DIRECTIONAL MARKINGS, HANDICAPPED MARKINGS AND OTHER MARKINGS AFTER THE NEW TRAFFIC COATING IS APPLIED AND COMPLETELY CURED.

ALTERNATE #2 - 100% REMOVAL AND REPLACEMENT OF THE RAMP EXPANSION JOINTS

SEE KEY NOTE 5. REMOVE AND REPLACE 100% OF THE EXISTING RAMP HORIZONTAL AND VERTICAL EXPANSION JOINTS AT ALL LEVELS. **NOTE:** REPLACEMENT OF EXPANSION JOINTS AT THE SKYWARD RAMPS BETWEEN LEVELS 'M' AND 'L' ARE TO BE CONSIDERED IN THE BASE BID.

CORROSION INHIBITOR/BONDING AGENT. PREPARE CONCRETE SUBSTRATE TO RECEIVE PATCHING MORTAR ACCORDING TO THE SPECIFICATIONS AND THE MANUFACTURER'S RECOMMENDATIONS. PLACE PATCHING MORTAR AS DIRECTED IN THE MANUFACTURER'S WRITTEN INSTRUCTIONS. APPLY A BOND COAT IF RECOMMENDED. FINISH AND CURE PATCH TO MATCH SURROUNDING SLAB TEXTURE.



1

BROWNING DAY MULLINS DIERDORF LEADERSHIP + DESIGN®

Browning Day Mullins Dierdorf Architects Architecture Landscape Architecture Planning Interior Design

626 North Illinois Street Indianapolis, Indiana 46204 Phone: (317) 635-5030 Website: www.bdmd.com

Delta Quad Holdings, LLC

Rau Construction Co. Construction Manager 9101 West 110th Street, Suite 150

Overland Park, Kansas 66210 Phone: (913) 642-6000 Website: www.website.com

Lawson Elser, Inc. Structural Engineer 650 East Carmel Drive, Suite 150

Carmel, Indiana 46032 Phone: (317) 574-5409 Website: www.lawsonelser.com

Hoss & Brown Engineers, Inc. MEP Engineer

11205 West 79th Street, Suite 102 Lenexa, Kansas 66214 Phone: (913) 362-9090 Website: www.h-be.com

SK Design Group, Inc. Civil Engineer 4600 College Boulevard, Suite 100

Overland Park, KS 66211 Phone: (913) 451-1818 Website: www.skdesigngroup.com

Matchline Design Group, LLC Interior Design 10300 North Central Expressway, Suite 335 Dallas, TX 75231


Phone: (972) 707-0568 Website: www.matchlinedesign.com

Garage Repair Plans dated January 25, 2019 are for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.


> CERTIFICATION GARAGE MAINTENANCE PACKAGE

The Grand Reserve






I










I









I

REPAIR 4 - SLAB FULL DEPTH SCALE: 3/4" = 1'-0"

SCALE: 3/4" = 1'-0"

2

I

BROWNING DAY MULLINS DIERDORF LEADERSHIP + DESIGN®

Browning Day Mullins Dierdorf Architects Architecture Landscape Architecture Planning Interior Design

626 North Illinois Street Indianapolis, Indiana 46204 Phone: (317) 635-5030 Website: www.bdmd.com

Delta Quad Holdings, LLC

Rau Construction Co. Construction Manager 9101 West 110th Street, Suite 150

Overland Park, Kansas 66210 Phone: (913) 642-6000 Website: www.website.com

Lawson Elser, Inc. Structural Engineer 650 East Carmel Drive, Suite 150

Carmel, Indiana 46032 Phone: (317) 574-5409 Website: www.lawsonelser.com

Hoss & Brown Engineers, Inc. MEP Engineer

11205 West 79th Street, Suite 102 Lenexa, Kansas 66214 Phone: (913) 362-9090 Website: www.h-be.com

SK Design Group, Inc. Civil Engineer 4600 College Boulevard, Suite 100

Overland Park, KS 66211 Phone: (913) 451-1818 Website: www.skdesigngroup.com

Matchline Design Group, LLC Interior Design 10300 North Central Expressway, Suite 335 Dallas, TX 75231

Phone: (972) 707-0568 Website: www.matchlinedesign.com

Garage Repair Plans dated January 25, 2019 are for general areas of structural repairs. These areas include scopes of work for bidding purposes. These plans also have recommendations for possible repair details to be made to the CIP and hollow core panel systems. These possible repair details are for reference only and are not engineered solutions. Engineered solutions to be provided by Contractors Engineer.

> CERTIFICATION GARAGE MAINTENANCE PACKAGE

The Grand Reserve

